

Rear mounting hole has limited access from above. Use machine screw with nut

474.00

H5 MOUNT LOCATIONS

The 3x mounting holes on the machine are 9mm diameter through. Choose mounting hardware that is appropriate for your benchtop.

2X Front mounting holes have access from above. Lag bolt or machine screw with nut

636.00

315-325mm
(not to scale)

FRONT BENCH EDGE

